

EETD Occurrence Reporting & Processing System (ORPS) Summary							Updated: 10/22/2008
Date	Location	PI	Work Lead	Facility No.	Dept.	Description (No injuries except where noted)	Corrective Action
6/21/2007	Field site	Melissa Lunden	Melissa Lunden	35	AS	Student Assistant received electric shock while working on lab-built gas sampling equipment. Probable energized ground due to faulty house wiring. Root cause: inadequate identification and control of hazards.	1. Investigate and correct problems with research equipment and electrical outlet. 2. Supplement the EETD Off-site Safety Review with a Statement of Field Work Safety Procedures. 3. EH&S develop task-based JHA methodology and process. 4. Lab-wide communication regarding reporting to medical after any shock. 5. LBNL develop an electrical apparatus acceptance process.
3/7/2005	Fremont, CA	Ashok Gadgil		27(?)	IE	Auto accident near Fremont while employee was enroute to field test site. Employee not at fault. Hospital evaluation: minor cuts and abrasions, and two broken ribs (weakened from previous non-work related injury).	1. Improve availability of information regarding what to do and who to contact in an emergency. (Website improvements.) 2. Re-educate key personnel on DOE notification procedures.
8/14/2003	UCB to 70-134	Rich Sextro	Tracy Thatcher	26	IE	Two Kr-85 sealed sources transported by researcher in personal car from Davis Hall to 70-134 in early June 2003. 70-134 not a posted Control Area.	1. Recover and ship sealed sources back to UCB. 2. Re-educate Department personnel. 3. Disseminate Lessons Learned Division-wide.
8/26/1993	62-238	?	?	?	AET(?)	Facilities maintenance worker exposed to laser light by entering rear door to laser lab. No injury resulted.	1. Curtail laser operations until rear door access control improved. 2. New signage on rear door. 3. Review of AHD for policy adherence.
11/2/1992	Nevada Research Site	Joe Klems	Guy Kelley	16	BT	Office trailer burglary. No DOE property stolen. Burglar broke front window, reached in, and took small personal tape player/radio.	1. Replace window glass. 2. Install window security bars on all remaining unsecured windows.
2/22/1992	Nevada Research Site	Joe Klems	Guy Kelley	16	BT	Office trailer burglary. \$464 stolen property and damage. \$300 stolen personal property. (3/5/92 delayed ORPS report.)	1. Door lock improvements. 2. Install window security bars on rear windows. 3. Improve equipment inventory. 4. Engrave ID info on major equipment & tools.
7/24/1991	73-110	Tica Novakov	Dick Schmidt(?)	21	AS	Isopropyl Alcohol fire. Extinguished in approx. 15 seconds by sprinkler system.	1. Redesign system. 2. Rebuild system. 3. Revise procedures and train users. 4. Post basic procedures memo.
7/22/1991	70-295	Elton Cairns	Kathy Striebel(?)	5a	AET	Acid burn to face. Injury: 1st degree burns to face.	1. Employee counseled. 2. Incident discussed at research group meeting. 3. Incident discussed at Division Project Leaders meeting.
3/29/1991	Nevada Research Site	Joe Klems	Guy Kelley	16	BT	Weather tower damaged when truck snagged guy wire.	1. Increase clearance below guy wire. 2. Block off low clearance area. 3. Improve visibility of guy wire.